

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/PWD Dt. 23-01-1970)

1. Name of the Officer : Arunkumar K S
2. Name of the school : Cristava Mahilalayam Public School
3. Location with name of Education District/ Sub District : Aluva, Ernakulam
4. Classification of Building as specified in column 4 of the application for fitness certificate and size : B.No. 594
: Permanent RCC building
: Three Storied building
: Details attached
5. Period for which the certificate is issued : 2025-2026
6. Nature of defects if any
 - h) Foundation and basement : Nil
 - i) Superstructure : Nil
 - j) Doors and Windows : Nil
 - k) Wood work wrought and put up : Nil
 - l) Roof : Nil
 - m) Flooring : Nil
 - n) Miscellaneous : Nil
7. Any major defects noticed which will render the building Unsafe in any manner : Nil
8. Whether maintenance works have been done properly : Yes
9. Whether the structure is sound or not for conducting classes : Sound normal weather conditions

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 21/05/25 and found to be fit to conduct classes, for the period Academic year 2025-2026 reasons stated above.

Place: KEEZHMAD

Date: 26/05/25



Assistant Engineer
Assistant Engineer
L.S.G.D. Section
Keerthi

Mary
Secretary

Arunkumar
11/06/2025

Principal
Cristava Mahilalayam Public School
Theerthapuzha P.O., Aluva - 683 105

{ Sheeted roof with ceiling , 2.76m height in class rooms and 3.00m height for yoga room }	-	6.10m x6.20m -9 Nos
	-	6.10m 3.00m -1 No
	-	6.00m x6.00m -1 No
	-	3.40m x2.80m -1 No



Assistant Engineer
L.S.G.D. Section
Keezhmad



Chomes
 11/06/2015

Principal

Christava Mahilalayam Public School
 Thottumugham P.O., Aluva - 683 105

Mary
Secretary